

OWNER: EVISAIR UK
ADDRESS: C/O SERENUS CONSEIL
 LUXEMBOURG L-1660
PHONE:
FAX:

OPERATOR: IXAIR
ADDRESS: 43, AVENUE DE L'EUROPE
 LE BOURGET 93350
PHONE: +33 1 30 08 91 41
FAX: + 33 1 30 08 91 25

OPERATOR: SERENUS CONSEIL
ADDRESS: 30 GRAND RUE
 LUXEMBOURG L-1660
PHONE:
FAX:

ANALYST: MOHAMED ACHOUR
EMAIL: MOHAMED.ACHOUR@CAMPSYSTEMS.EU

+33 (0) 1.55.93.45.80 (OFFICE)
 +33 (0) 1.53.01.66.18
 (EFAX-CARDS)
 WWW.CAMPSYSTEMS.COM

PROJECTED : 12 MOS. to 25-SEP-2019

AIRCRAFT SERIAL/REGNO: 525-0082/N525LW **MODEL:** 525 - CITATION JET **MANUFACTURER:** TEXTRON AVIATION INC.

DATES	LAST ACTUALS	PROJECTED
CERTIFICATION DATE: 14-DEC-1994	3090 A/C HRS as of 07-SEP-2018	3330
	3172 AFL as of 07-SEP-2018	3376
	1331 ACH as of 31-JUL-2018	1451

ENGINE NO. 1 SERIAL/PART: 1152/45700-104 **MODEL:** FJ44-1A **MANUFACTURER:** WILLIAMS INTERNATIONAL

INSTALLED ON 10-JUL-2000	LAST ACTUALS	PROJECTED
1411 ENG. HRS 1562 A/C HRS	2947:12 ENG. HRS as of 07-SEP-2018	3187:12
ENC	3003 ENC as of 07-SEP-2018	3207

ENGINE NO. 2 SERIAL/PART: 1185/45700-104 **MODEL:** FJ44-1A **MANUFACTURER:** WILLIAMS INTERNATIONAL

INSTALLED ON 19-MAY-2000	LAST ACTUALS	PROJECTED
1433 ENG. HRS 1532 A/C HRS	2990:30 ENG. HRS as of 07-SEP-2018	3230:30
ENC	3068 ENC as of 07-SEP-2018	3272



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
256006	LAVATORY LIFE VEST								
25.200	P/N: P01074-103 S/N: 13070090036 REF: GENERIC NO REF	MOS HRS/MSC O/C AFL				01-AUG-2018 M		OVD	
SB FJ44-72-034 R06	NO. 2 ENGINE - ENGINE - GEARBOX ASSEMBLY - INCORPORATE CARBON SEAL MAGNET KEEPERS, SERVICE BULLETIN							MANDATORY	
	REF: BULLETINS	MOS HRS/MSC DUE ENC				(2615) 2714:30 M		OVD	
SB FJ44-72-034 R06	NO. 1 ENGINE - ENGINE - GEARBOX ASSEMBLY - INCORPORATE CARBON SEAL MAGNET KEEPERS, SERVICE BULLETIN							MANDATORY	
	REF: BULLETINS	MOS HRS/MSC DUE ENC				(2563) 2705:48 M		OVD	
SB FJ44-72-035 R03	NO. 2 ENGINE - NO. 1 CARBON SEAL AND NO.1 CARBON SEAL RUNNER - REPLACE, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC				(2930:24) 3029:54 M		OVD	
SB FJ44-72-035 R03	NO. 1 ENGINE - NO. 1 CARBON SEAL AND NO.1 CARBON SEAL RUNNER - REPLACE, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC				(2907:54) 3050:42 M		OVD	
SB FJ44-72-039 R05	NO. 1 ENGINE - HP COMPRESSOR ROTOR - REWORK BACKWALL, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2907:54) 3050:42 M (3198) 3367 M		OVD 195	
SB FJ44-72-039 R05	NO. 2 ENGINE - HP COMPRESSOR ROTOR - REWORK BACKWALL, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2930:24) 3029:54 M (3244) 3348 M		OVD 176	

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
 * - Estimated Due (applies to New Requirement)

Due List

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE <small>(ENG) A/C</small>	MAX LIMIT	DISPOSITION <small>TIME REMAINING</small>	EST. DUE
SB FJ44-72-076 R01	NO. 2 ENGINE - IP COMPRESSOR STATOR - REWORK, SERVICE BULLETIN							OPTIONAL	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2930:24) 3029:54 M (3244) 3348 M		OVD 176	
SB FJ44-72-076 R01	NO. 1 ENGINE - IP COMPRESSOR STATOR - REWORK, SERVICE BULLETIN							OPTIONAL	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2907:54) 3050:42 M (3198) 3367 M		OVD 195	
SB FJ44-72-083 R05	NO. 2 ENGINE - UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R06), SERVICE BULLETIN							OPTIONAL	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2930:24) 3029:54 M (3244) 3348 M		OVD 176	
SB FJ44-72-083 R05	NO. 1 ENGINE - UPGRADE FJ44-1A GEARBOX (8K MAGSEAL) TO SPRING LOADED CONFIGURATION (SUPERSEDED BY FJ44-72-083 R06), SERVICE BULLETIN							OPTIONAL	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2907:54) 3050:42 M (3198) 3367 M		OVD 195	
SB FJ44-72-087 R05	NO. 2 ENGINE - BLEED VALVE SHAFT - REPLACE, SERVICE BULLETIN							OPTIONAL	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2930:24) 3029:54 M (3244) 3348 M		OVD 176	
SB FJ44-72-087 R05	NO. 1 ENGINE - BLEED VALVE SHAFT - REPLACE, SERVICE BULLETIN							OPTIONAL	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2907:54) 3050:42 M (3198) 3367 M		OVD 195	
SB FJ44-72-108 R01	NO. 2 ENGINE - ACCESSORY DRIVE SHAFT - REPLACE, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2930:24) 3029:54 M		OVD	

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
* - Estimated Due (applies to New Requirement)



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
SB FJ44-72-108 R01	NO. 1 ENGINE - ACCESSORY DRIVE SHAFT - REPLACE, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2907:54) 3050:42 M		OVD	
SB FJ44-72-109	NO. 2 ENGINE - ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC				(2930:24) 3029:54 M		OVD	
SB FJ44-72-109	NO. 1 ENGINE - ENGINE - 1ST REDUCTION BEVEL GEAR BALL BEARING - REPLACE, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC				(2907:54) 3050:42 M		OVD	
SB FJ44-72-144	NO. 2 ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE / REWORK, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2930:24) 3029:54 M (3244) 3348 M		OVD 176	
SB FJ44-72-144	NO. 1 ENGINE - DIFFUSER CASE ASSEMBLY - REPLACE / REWORK, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2907:54) 3050:42 M (3198) 3367 M		OVD 195	
SB FJ44-72-148	NO. 2 ENGINE - GEARBOX ASSEMBLY - REWORK 2ND REDUCTION BEARING HOUSING, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2930:24) 3029:54 M (3244) 3348 M		OVD 176	
SB FJ44-72-148	NO. 1 ENGINE - GEARBOX ASSEMBLY - REWORK 2ND REDUCTION BEARING HOUSING, SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC DUE ENC			(EFF)	(2907:54) 3050:42 M (3198) 3367 M		OVD 195	

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
 * - Estimated Due (applies to New Requirement)



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
SB FJ44-79-011 R04	NO. 2 ENGINE - MAGNETIC SELF-CLOSING VALVE - REPLACE, SERVICE BULLETIN						MANDATORY	
	REF: BULLETINS	MOS HRS/MSC DUE ENC		(EFF)	(2930:24) 3029:54 M		OVD	
SB FJ44-79-011 R04	NO. 1 ENGINE - MAGNETIC SELF-CLOSING VALVE - REPLACE, SERVICE BULLETIN						MANDATORY	
	REF: BULLETINS	MOS HRS/MSC DUE ENC		(EFF)	(2907:54) 3050:42 M		OVD	
5-12-12	INSPECTION DOCUMENT 12 (14 CFR 91.207)							
	REF: TLMC 5-12-12	MOS 12 HRS/MSC AFL			12-OCT-2017 3030 3132		17d	12-OCT-2018
	WO: 18JET088							
341057	CALIBRATION TEST LEFT ADC/ALT UNIT (91.411): INSPECTION DOCUMENT 13							
34.580	P/N: 70251N01D02 S/N: 03041009BC REF: GENERIC NO REF	MOS 24 HRS/MSC AFL			14-OCT-2016	14-OCT-2018	19d	14-OCT-2018
	WO: 18JET088							
341058	CALIBRATION TEST RIGHT ADC/ALT UNIT (91.411): INSPECTION DOCUMENT 13							
34.590	P/N: 70251N01D02 S/N: 03051016BC REF: GENERIC NO REF	MOS 24 HRS/MSC AFL			14-OCT-2016	14-OCT-2018	19d	14-OCT-2018
	WO: 18JET088							
341060	INSPECT RVSM SKIN WAVINESS CHECK: INSPECTION DOCUMENT 13							
34.595	REF: GENERIC NO REF	MOS 24 HRS/MSC AFL			14-OCT-2016	14-OCT-2018	19d	14-OCT-2018
	WO: 18JET088							

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
 * - Estimated Due (applies to New Requirement)



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
341106	CALIBRATION TEST STANDBY ENCODING ALTIMETER (FAR 91.411): INSPECTION DOCUMENT 13							FAR	
34.075	P/N: 44929-935 S/N: 1185 REF: See Workcard	MOS HRS/MSC AFL	24			14-OCT-2016 14-OCT-2018		19d	14-OCT-2018
WO: 18JET088									
B341011	FUNCTIONAL CHECK LEFT PITOT-STATIC SYSTEMS: INSPECTION DOCUMENT 13								
34.530		MOS HRS/MSC AFL	24			14-OCT-2016 14-OCT-2018		19d	14-OCT-2018
REF: AMM 34-11-02									
WO: 18JET088									
B341011	FUNCTIONAL CHECK RIGHT PITOT-STATIC SYSTEMS: INSPECTION DOCUMENT 13								
34.530		MOS HRS/MSC AFL	24			14-OCT-2016 14-OCT-2018		19d	14-OCT-2018
REF: AMM 34-11-02									
WO: 18JET088									
B345401	CALIBRATION CHECK NO. 1 TRANSPONDER ATC SYSTEM (FAR 91.413): INSPECTION DOCUMENT 13							FAR	
34.430	P/N: 010-00293-21 S/N: 84406595 REF: See Workcard	MOS HRS/MSC AFL	24			14-OCT-2016 14-OCT-2018		19d	14-OCT-2018
WO: 18JET088									
B345401	CALIBRATION CHECK NO. 2 TRANSPONDER ATC SYSTEM (FAR 91.413): INSPECTION DOCUMENT 13							FAR	
34.430	P/N: 066-01141-6101 S/N: 1168 REF: See Workcard	MOS HRS/MSC AFL	24			14-OCT-2016 14-OCT-2018		19d	14-OCT-2018
WO: 18JET088									
351004	LEFT ALTITUDE PRESSURE SWITCH								
35.040	P/N: P24031 S/N: SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	60			17-JUL-2000 1562 19-OCT-2018 M		24d	19-OCT-2018
TSN:0									

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
* - Estimated Due (applies to New Requirement)



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
5-12-10	INSPECTION DOCUMENT 10								
	REF: TLMC 5-12-10	MOS HRS/MSC AFL	36 1200 +2m +30		19-OCT-2015 2810:38 2952	19-OCT-2018 M 4010:38	19-DEC-2018 4040:38	24d 920:38 (+61) (+30)	19-OCT-2018
5-12-11	INSPECTION DOCUMENT 11								
	REF: TLMC 5-12-11	MOS HRS/MSC AFL	36 1200 +2m +30		19-OCT-2015 2810:38 2952	19-OCT-2018 M 4010:38	19-DEC-2018 4040:38	24d 920:38 (+61) (+30)	19-OCT-2018
ST-3400-102	ICA TAX SANDEL ST-3400-102: INSPECT SYSTEM FOR SECURITY, EVIDENCE OR OVERHEATING AND OPERATION							CUSTOMER CODE	
	REF:	MOS HRS/MSC AFL	36 (s) 1200		19-OCT-2015 2810:38	19-OCT-2018 M 4010:38 M		24d 920:38	19-OCT-2018
256006	NO. 3 LIFE VEST								
25.170	P/N: P01074-103 S/N: 13103380031 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			19-NOV-2018 M		55d	19-NOV-2018
256006	NO. 4 LIFE VEST								
25.180	P/N: P01074-103 S/N: 13103380034 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			19-NOV-2018 M		55d	19-NOV-2018
256006	NO. 6 LIFE VEST								
25.180	P/N: P01074-103 S/N: 13103380032 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			19-NOV-2018 M		55d	19-NOV-2018
256006	CO-PILOT LIFE VEST								
25.200	P/N: P01074-103 S/N: 13103380033 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			19-NOV-2018 M		55d	19-NOV-2018

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
 * - Estimated Due (applies to New Requirement)



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE <small>(ENG) A/C</small>	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
052001	NO. 2 ENGINE - FJ44 CHECK 1	MOS HRS/MSC 300 ENC	+30		19-OCT-2015 2711:08 2848	(3027:42) 3127:12	3057:42	37:12 (+30)	20-NOV-2018
	REF: LM 05-20-00								
052001	NO. 1 ENGINE - FJ44 CHECK 1	MOS HRS/MSC 300 ENC	+30		19-OCT-2015 2667:50 2783	(2986:06) 3128:54	3016:06	38:54 (+30)	23-NOV-2018
	REF: LM 05-20-00								
5-12-02	INSPECTION DOCUMENT 02	MOS HRS/MSC AFL	12 +2m		01-DEC-2017 3037:18 3138	01-DEC-2018	01-FEB-2019	67d (+62)	01-DEC-2018
	REF: TLMC 5-12-02								
5-12-33	INSPECTION DOCUMENT 33	MOS HRS/MSC 300 AFL	12 +2m +30		01-DEC-2017 3037:18 3138	01-DEC-2018 3337:18	01-FEB-2019 3367:18	67d (+62) 247:18 (+30)	01-DEC-2018
	REF: TLMC 5-12-33								
B262201	FUNCTIONAL (WEIGHT) CHECK COCKPIT PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 02	MOS HRS/MSC AFL	12 +2m		01-DEC-2017 3037:18 3138	01-DEC-2018	01-FEB-2019	67d (+62)	01-DEC-2018
26.060	P/N: C352TS S/N: Y-17341 REF: AMM 26-22-00								
5-12-36	INSPECTION DOCUMENT 36	MOS HRS/MSC AFL	6 +2m		08-JUN-2018 3059 3153	08-DEC-2018	08-FEB-2019	74d (+62)	08-DEC-2018
	REF: TLMC 5-12-36								
256006	NO. 5 LIFE VEST	MOS HRS/MSC O/C AFL				18-DEC-2018 M		84d	18-DEC-2018
25.180	P/N: P01074-103 S/N: 13112070004 REF: GENERIC NO REF								

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
* - Estimated Due (applies to New Requirement)



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
350002	RESTORATION (HYDROSTATIC TEST) OXYGEN BOTTLE								
35.010	P/N: 176274-22 S/N: 1339-1651 REF: AMM 35-00-00	MOS HRS/MSC AFL	60		01-JAN-2014	01-JAN-2019		98d	01-JAN-2019
057102	NO. 1 ENGINE - INSPECT ENGINE COMPRESSOR WASH								
	REF:	MOS HRS/MSC ENC	150		01-DEC-2017 2894:30 2969	(3044:30) 3187:18		97:18	19-FEB-2019
057102	NO. 2 ENGINE - INSPECT ENGINE COMPRESSOR WASH								
	REF:	MOS HRS/MSC ENC	150		01-DEC-2017 2937:48 3034	(3087:48) 3187:18		97:18	19-FEB-2019
5-12-18	INSPECTION DOCUMENT 18								
	REF: TLMC 5-12-18	MOS HRS/MSC AFL	150	+30	01-DEC-2017 3037:18 3138	3187:18	3217:18	97:18 (+30)	19-FEB-2019
A361002	DETAILED INSPECTION LEFT B/A PRECOOLER ASSEMBLY : INSPECTION DOCUMENT 22								
36.020	P/N: 8161-5 - 9914402-6 S/N: S4883-T0931 REF: AMM 36-10-01	MOS HRS/MSC AFL	300	+30	14-OCT-2016 2917:25 3043	3217:25	3247:25	127:25 (+30)	06-APR-2019
A361002	DETAILED INSPECTION RIGHT B/A PRECOOLER ASSEMBLY : INSPECTION DOCUMENT 22								
36.020	P/N: 8161-5 - 9914402-6 S/N: S4883-T0970 REF: AMM 36-10-01	MOS HRS/MSC AFL	300	+30	14-OCT-2016 2917:25 3043	3217:25	3247:25	127:25 (+30)	06-APR-2019
256006	PILOT LIFE VEST								
25.200	P/N: P01074-103 S/N: 14051350044 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C			01-JUN-2019 M		249d	01-JUN-2019

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
* - Estimated Due (applies to New Requirement)



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
D243201	FUNCTIONAL CHECK MAIN BATTERY NICKEL-CADMIUM BATTERY(CAPACITY CHECK): INSPECTION DOCUMENT 17								
24.250	P/N: 30978-002 S/N: 11002440 REF: See Workcard	MOS HRS/MSC AFL	12 400		01-JUN-2018 3059 3153	01-JUN-2019 3459		249d 369	01-JUN-2019
21-USER-11-01	EVAPORATOR COIL ASSEMBLY INSPECT REFRIGERANT PLUMBING FOR LEAKAGE INSPECT COIL FINS FOR CLEANLINESS AND DAMAGE INSPECT COLD AIR DUCTING FOR LEAKING CRACKS OR DAMAGE							CUSTOMER CODE	
	P/N: PN S/N: SN-UNKNOWN REF:	MOS HRS/MSC AFL	12		08-JUN-2018 3059 3153	08-JUN-2019		256d	08-JUN-2019
21-USER-12-01	EVAPORATOR HOUSING ASSEMBLY INSPECT SEAM BETWEEN SHROUD ASSEMBLY AND ESCUTCHEON FOR SIGNS OF SEPARATION AND CONDENSATE LEAKAGE. INSPECT FOR CLEANLINESS AND DAMAGE/INTEGRITY. INSPECT CONDENSATE DRAIN, MAKING SURE HOLE IS CLEAR AND SECURE.							CUSTOMER CODE	
	P/N: PN S/N: SN-UNKNOWN REF:	MOS HRS/MSC AFL	12		08-JUN-2018 3059 3153	08-JUN-2019		256d	08-JUN-2019
21-USER-13-01	EXPANSION VALVE INSPECT FOR CLEANLINESS AND DAMAGE/INTEGRITY							CUSTOMER CODE	
	P/N: PN S/N: SN-UNKNOWN REF:	MOS HRS/MSC AFL	12		08-JUN-2018 3059 3153	08-JUN-2019		256d	08-JUN-2019
21-USER-14-01	CONDENSER COIL ASSEMBLY INSPECT REFRIGERANT PLUMBING FOR LEAKAGE INSPECT COIL FINS FOR CLEANLINESS AND DAMAGE INSPECT AIR DUCTING FOR LEAKING CRACKS OR DAMAGE							CUSTOMER CODE	
	P/N: PN S/N: SN-UNKNOWN REF:	MOS HRS/MSC AFL	12		08-JUN-2018 3059 3153	08-JUN-2019		256d	08-JUN-2019
21-USER-15-01	CONDENSER HOUSING ASSEMBLY INSPECT FOR CLEANLINESS AND DAMAGE/INTEGRITY.							CUSTOMER CODE	
	P/N: PN S/N: SN-UNKNOWN REF:	MOS HRS/MSC AFL	12		08-JUN-2018 3059 3153	08-JUN-2019		256d	08-JUN-2019

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
* - Estimated Due (applies to New Requirement)



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
21-USER-16-01	AXIAL FAN ASSEMBLY INSPECT FOR CLEANLINESS AND DAMAGE/INTEGRITY VERIFY THAT FAN BLADE IS CLEAN AND OPERATES VIBRATION FREE. MOTOR BRUSH INSPECTION (1134620-3 CONDENSER ASSEMBLY ONLY)							CUSTOMER CODE	
	P/N: PN	MOS	12			08-JUN-2018	08-JUN-2019	256d	08-JUN-2019
	S/N: SN-UNKNOWN	HRS/MSC				3059			
	REF:	AFL				3153			
		ACH	500			1329	1829	498	
21-USER-17-01	BLOWER ASSEMBLY BLOWER ASSEMBLY INSPECT FOR CLEANLINESS AND DAMAGE/INTEGRITY VERIFY THAT BLOWER WHEEL IS CLEAN AND OPERATES VIBRATION FREE. MOTOR BRUSH INSPECTION (FWD EVAPORATOR 1134300-3 ONLY)							CUSTOMER CODE	
	P/N: PN	MOS	12			08-JUN-2018	08-JUN-2019	256d	08-JUN-2019
	S/N: SN-UNKNOWN	HRS/MSC				3059			
	REF:	AFL				3153			
		ACH	1000			1329	2329	998	
SL CIL-26-01 R01	FIRE PROTECTION - FIRE EXTINGUISHER BOTTLE CARTRIDGE GROUND STUD TORQUING, SERVICE LETTER							MANDATORY	
		MOS	36			16-JUN-2016	16-JUN-2019	264d	16-JUN-2019
		HRS/MSC	1200			2868	4068	978	
	REF: BULLETINS	AFL							
052004	NO. 2 ENGINE - FJ44 CHECK 4								
		MOS				14-DEC-1994			05-AUG-2019
		HRS/MSC	4500	+50		0	(4000) 4099:30 M	4050	1009:30 (+50)
	REF: See Workcard	ENC	5250			0	(3244) 3348	176	
SB FJ44-72-130 R01	NO. 2 ENGINE - HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02), SERVICE BULLETIN							RECOMMENDED	
		MOS				(EFF)			05-AUG-2019
		HRS/MSC	DUE						
	REF: BULLETINS	ENC					(3244) 3348 M	176	
5-12-01	INSPECTION DOCUMENT 01								
		MOS				09-JUN-2017			09-AUG-2019
		HRS/MSC	300	+30		2999:37	3299:37	3329:37	209:37 (+30)
	REF: TLMC 5-12-01	AFL				3107			

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
 * - Estimated Due (applies to New Requirement)



Due List

All Items

525 - CITATION JET S/N 525-0082 (N525LW): 3090 HRS, 3172 AFL as of 07-Sep-2018

Operator: IXAIR

Report Date: 25-SEP-2018

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
256005	ELT BEACON BATTERY PACK							LIFE LIMIT	
25.040	P/N: 452-0133 S/N: 363638-015 REF: AMM 25-61-02 Manufacture Date:01-SEP-2014	MOS HRS/MSC AFL	60			20-NOV-2014 01-SEP-2019 TSN:0 2709:22 TSN:0 2865		341d	01-SEP-2019
052004	NO. 1 ENGINE - FJ44 CHECK 4								
	REF: See Workcard	MOS HRS/MSC ENC	4500 +50 5250			14-DEC-1994 0 (4000) 4142:48 M 0 (3198) 3367	4050	1052:48 195 (+50)	08-SEP-2019
SB FJ44-72-130 R01	NO. 1 ENGINE - HP COMPRESSOR ROTOR - INSPECTION (SUPERSEDED BY FJ44-72-130 R02), SERVICE BULLETIN							RECOMMENDED	
	REF: BULLETINS	MOS HRS/MSC ENC	DUE			(EFF) (3198) 3367 M		195	08-SEP-2019
055603A	INSPECT RIGHT CKPT SIDE WINDOW INSP-300 HRS.								
	REF:	MOS HRS/MSC AFL	24 300			12-OCT-2017 12-OCT-2019 3030 3330 3132		382d 240	25-SEP-2019
5-12-MA	INSPECTION DOCUMENT MA							AIRWORTHINESS	
	REF: TLMC 5-12-MA	MOS HRS/MSC AFL	300			12-OCT-2017 3030 3132	3330	240	25-SEP-2019

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
 * - Estimated Due (applies to New Requirement)



Discrepancy Due List Report

MODEL: 525 - CITATION JET SERIAL: 525-0082 RegNo: N525LW

Report Date: 25-SEP-2018

DISCR # DATE LOGGED PART/SERIAL	CATEGORY	ATA	DESCRIPTION	UNIT	INTERVAL	LOGBOOK TIMES	LOGBOOK Ref.	NEXT DUE (x Ext)	TIME REMAINING	EST. DATE
---------------------------------------	----------	-----	-------------	------	----------	------------------	-----------------	---------------------	-------------------	-----------

NO DATA FOUND

Discrepancy Type:

(#) - RTS-UPDATE PENDING

(!) - RTS-UPDATE OVERDUE

© CAMP SYSTEMS